

PAGE 1 OF 2



Cambria Environmental Technology, Inc. 5900 Hollis Street, Suite A Emeryville, CA 94608 Telephone: (510) 420-0700

Fax: (510) 420-9170

Chevron Environmental Management Company BORING/WELL NAME MW-3D CLIENT NAME JOB/SITE NAME Chevron #9-5121 **DRILLING STARTED** 11-May-05 DRILLING COMPLETED 18-May-05 LOCATION 875 Main Street, Fortuna, CA WELL DEVELOPMENT DATE (YIELD) PROJECT NUMBER 31H-1913 **DRILLER** Woodward Drilling Co. **GROUND SURFACE ELEVATION** Not Surveyed DRILLING METHOD Hollow-stem auger TOP OF CASING ELEVATION Not Surveyed BORING DIAMETER SCREENED INTERVAL 35 to 45 fbg LOGGED BY M. Terry **DEPTH TO WATER (First Encountered)** 8.0 fbg (11-May-05) REVIEWED BY B. Foss, PG # 7445 **DEPTH TO WATER (Static)** NA

REMARKS Cleared with airknife to 8 fbg. CONTACT DEPTH (fbg) GRAPHIC LOG (mdd) BLOW EXTENT DEPTH (fbg) Ś SAMPLE U.S.C.8 LITHOLOGIC DESCRIPTION WELL DIAGRAM PID (Asphalt surface. Cleared to 8 fbg with air knife; subsurface material consisted of soft, dry, gravelly clay with moderate plasticity and moderate permeability; groundwater first encountered CL 8.0 10.0 10 3 6 12 Clayey SILT: Dark brown; dry; 70% silt, 30% clay; ML 0 MW-3D moderate plasticity; low estimated permeability; rootlets at 11.5 @10.5 15.0 12 17 20 Clayey SILT: Light tan with orange mottling; dry; 70% ML MW-3D 0 Portland Type silt, 30% clay; moderate plasticity; low estimated 16.5 @15.5 permeability. 1/11 20.0 Sandy SILT: Gray w/orange mottling; dry; soft; 65% silt, 25% fine sand, 10% clay; low plasticity; moderate ML 0 MW-3D 21.5 DEFAULT GDT @20.5 estimated permeability. WELL LOG (PID) 1:\9-5121~1\GINT\MW-1D - MW-6D.GPJ 25.0 15 18 27 Clayey SILT: Gray w/orange mottling; dry; soft; 60% MI MW-3D silt, 40% clay; moderate plasticity; low estimated 26.5 @25.5 permeability 30.0 10 12 14 Sandy SILT: Gray orange; dry; 60% silt, 40% sand; MW-3D ML low plasticity; high estimated permeability 31.5 @30.5 Bentonite Seal Lonestar Sand 35.0

Continued Next Page

BORING/WELL LOG



Cambria Environmental Technology, Inc. 5900 Hollis Street, Suite A Emeryville, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

| CLIENT NAME | Chevron Environmental Management Company | BORING/WELL NAME | MW-3D |
|---------------|--|--------------------|-----------|
| JOB/SITE NAME | Chevron #9-5121 | DRILLING STARTED | 11-May-05 |
| LOCATION | 875 Main Street Fortuna CA | DRILLING COMPLETED | 18-May-05 |

| Continued from Previous Page | | | | | | | | | | |
|---|----------------|----------------|--------|----------------|----------|----------------|--|------------------------|---|--|
| PID (ppm) | BLOW | SAMPLE ID | EXTENT | DEPTH (fbg) | U.S.C.S. | GRAPHIC LOG | LITHOLOGIC DESCRIPTION | CONTACT DEPTH (fbg) | WELL DIAGRAM | |
| 0 | 14 14 18 | MW-3D @35.5 | | | ML | | <u>Sandy SILT</u> : Gray orange; dry; 60% silt, 40% sand; low plasticity; high estimated permeability. | 36.5 | #2/12 | |
| 0 | 20 50/5" | MW-3D @40.5 | | 40 | ML | | Sandy SILT: Gray orange; dry; 60% silt, 40% sand; low plasticity; high estimated permeability. | _40.0 _41.5 | ■ 2"-diam., 0.010" Slotted Schedule 40 PVC | |
| 0 | 27 50/5" | MW-3D @45.5 | | - 45 | SW | 0 0 0 0 | Gravelly SAND: Dark brown; wet; 85% coarse to fine sand, 15% gravel; no plasticity; high estimated permeability. | _45.0 _46.5 | Bottom of Boring @ 45 fbg | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| 8/4/05 | | | | | | | | | | |
| WELL LOG (PID) INSCRIZITION NWW-1D - MW-5D.GFZ DEFAULTGDT 8/4/05 | | | | | | | | | | |
| -VAIN UI - NAINA - III - NA | | | | : | | | | | | |
| LOG (PID) 1:8-51212 | | | | | | | | | | |
| WELL | | | | | | | | | | |